

**Revision and Errata List—January 2020**

***AISC Seismic Provisions for Structural Steel Buildings, July 12, 2016***

The following list represents corrections incorporated in the January 2020 revision of the 2016 *AISC Seismic Provisions for Structural Steel Buildings*.

<b>Page(s)</b>	<b>Item</b>
9.1-243	Remove the heading “3. Continuity Plate Welding.”
9.1-291	In Fig. C-F3.4, definition of $\theta_p$ , replace $\Delta_p h$ with $\Delta_p/h$